PROPOSED NRC-DEVELOPED ADMINISTRATIVE JPMS

WITH FACILITY AND NRC COMMENTS

FOR THE PRAIRIE ISLAND INITIAL EXAMINATION - AUGUST 2002

•	Worksheet
Facility: Prairie Island	Task No:
Task Title: Conduct Control Board	Job Performance Measure No: SRO/RO
Walkdown for Shift Turnov	<u>A.1.a</u>
K/A Reference: <u>2.1.3 [3.0/3.4]</u>	
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing: Simulated Performance Actual Perf	ormance X Classroom Simulator X Plant
READ TO THE EXAMINEE	
cues. When you complete the task such measure will be satisfied	n steps to simulate or discuss, and provide initiating ccessfully, the objective for this job performance
Initial Conditions:	Lyprider Remardentar
- You are the on-coming Unit 1	Spender Remarks off-going with Shift-Spender (180)/Unit 1 were on 12 hours ago
 You are relieving the watch you 	were on 12 hours ago
Unit 1 is at 96% power with no	testing or other evolutions in progress
✓ Unit 1 is at 96% power with no to Task Standard: 100 IDENTIFY all dis SRO: EVALUA	crepancies on the Main Control Board.
SRO: EVALUA	TE any Tech Specs NOT met (if any) and associated
actions	
RO: DISCUSS	S any Tech Specs NOT met (if any)
Required Materials: 1. SRO: Unit 1	Shift Supervisor Turnover Log
2. RO: Unit 1	LPEO / PEO Turnover Log
3. Technical Sp	ecifications
General References: 1. SWI O-0, "Co	
Section 3.7.2	2, Rev 0
	hift Organization, Operations & Turnover, Rev 45
3. SRO: Unit 1	Shift Supervisor Turnover Log
4. RO: Unit 1	LPEO / PEO Turnover Log
5. Technical Sp	ecifications
Initiating Cues:	
 Perform a walkdown of the NSS 	SS portions of the Main Control Boards as required per
•	ns", Attachment 14, Section 3.7.2 and the Turnover Log
- You will be given 20 minutes for	r the walkdown of the NSSS portions of the Main Control
Beards = IDENTIFY and of	perstant limitedant or contains that you have . In any operational limitetions or contains that you have libouse any discrepancies or problems noted:
When you are finished we will d	House any discrepancies or problems noted:
▼	h Specs NOT met (if any) and associated actions
 RO: DISCUSS any Tech 	· · · · · · · · · · · · · · · · · · ·
 You are relieving the watch you 	were on 12 hours ago functional Talburd to touch the
Unit 1 is at 90% power with no 1	esting or other evolutions in progress Main contral Boards during
	testing or other evolutions in progress Main Control Bounds during the two halfs and during the two halfs and sounds during the two over
Time Critical Task: YES/NO Alterr	late Path: YES/ <u>NO</u>
Maraka T	
Validation Time: Minutes Time	Started Time Finished:
	Started Time Finished:

never Charges

		Concor	glalos	
Appe	ndix C	2	Form ES-C-1 (R8, S1)
	PERFORMANC	E INICODMAT		
Deno	ote critical steps with BOLD)		ION	
_1	Performance step: CRITICAL STEP		SAT/UNSAT	
PERF	ORM Main Control Board walkdown an e Main Control Boards.	d IDENTIFY	all discrepancies or proble	ems , or concern
tand	ard:		-	
ERF robk	ORMS Main Control Board walkdown a ems on the Main Control Boards.	and IDENTIFI	ES all discrepancies or	Hons
RO: 0:	EVALUATE any Tech Specs NOT met DISCUSS any Tech Specs NOT met	and associat	ed actions	
he fo	ollowing discrepancies or problems wil		d: . Ts 3.3, A. 1. b (4) and	
•	DISCREPANCY 11 Accumulator pressure at 600 psig	∫TS or	ECH SPEC AFFECTED 3.3.A.2.e - 1 hour LCO, be in HSD within 6 hours SD within 30 hours	and
المارا	RHR Supply to SI Pump Suction Valve MV-32206(8816A) and MV-32207(8816E indicate open by Monitor Lights on "5 I Note Ready" Panel	3) 1 1	3.3.A.1.g(2) and TS 3.0.C nour LCO, or be in HSD wi nours and CSD in next 30 I	thin
(S)	PRZR PORV Block Valves MV-32195 and MV-32196 de-energized EVALUATOB NOTE: Valves deenergized closed but can NOT tell if open or closed from Control Board Indications JATOR NOTE:	and r	3.1.A.2.c(1)(b) 5 - 1 hour L be in HSD within 6 hours : ا50°F in aext -6 hours احالاسم	CO, from and who charge reflect different toch spin pook vis
e sa Dand I 3 of	fety significance and Tech Specs for the devaluated by the SRO to receive full of 3 discrepancies must be found for the	redit for eac	h problem identified.	the
omme	ent:			
	- For RO, ask a following que that are in effect.	estmu abo	ut operational limitations	(if any)
-	- For SRO, when following gue that are in effect.	ntion to E	VALUATE operational lim	iohons life

Change in former of TAM. Change to a followyo quarton instead of an Imbieting Que.

Appendix C	3	Form ES-C-1 (R8, S1)
	VERIFICATION OF COMPLETI	ON
Job Performance Measure	No	
Examinee's Name:		
Examiner's Name:		
Date performed:		
Facility Evaluator:		
Number of attempts:		
Time to complete:		
Question Documentation:		
Question:		
Response:		

Result: SAT or UNSAT

Examiner's signature and date: _____

Initial Conditions:

You are the on-coming Unit 1(SRO)(RO) You are relieving the watch you were on 12 hours ago Unit 1 is at 90% power with no testing or other evolutions in progress

Initiating Cues:

- Perform a walkdown of the NSSS portions of the Main Control Boards as required per SWI O-0, "Conduct of Operations", Attachment 14, Section 3.7.2 and the **Turnover Log**
- You will be given 20 minutes for the walkdown of the NSSS portions of the Main Control Boards
- When you are finished we will discuss any discrepancies or problems noted:
 - SRO: EVALUATE any Tech Specs NOT met (if any) and associated actions
 - RO: DISCUSS any Tech Specs NOT met (if any)
- You are relieving the watch you were on 12 hours ago
- Unit 1 is at 90% power with no testing or other evolutions in progress
 - IDENTIFY any operational limitations or concerns that you have _ I will write down any operational limitation or concerns that you have identified of

- All lights have been ventied to be furtional

- You are NOT allowed to touth the Man Control Boards

during the temover

Concer. Changes incorporated Continental. Minkor

(Omplate 1 1119 Comments 1119

(1) dIA TUST 10 092

Jacodun Mardul

Then spectures and ellen der counting and ellen

Αp	pen	dix	C

Job Performance Measure Worksheet

Form ES-C-1 (R8, S1)

Facility: Prairie Island	Task No:
Task Title: Determine Maximum RCS Vent Time	Job Performance Measure No: SRO A.1.a
K/A Reference: <u>K/A 2.1.23 [3.9/4.0]</u>	
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing:	
Simulated Performance Actual Performance _X	_ Classroom Simulator _X Plant
READ TO THE EXAMINEE	
I will explain the initial conditions, which steps to sir cues. When you complete the task successfully, the measure will be satisfied. Initial Conditions:	mulate or discuss, and provide initiating ne objective for this job performance
The Control Room has been evacuated due to a fire. Both Units are being cooled down to Cold Shutdown in Attachment M has been implemented for Unit 2 due to Present RCS mess were 1750.	the presence of voids in the Reactor Vessel.
Task Standard: Maximum RCS venting time ca	alculated to be 40 seconds. 12 12 milly kg
Required Materials: Copy of F5 Appendix B, Attach Copy of F5 Appendix B, Figure	nment M, Page 3 8
General References: F5 Appendix B	
nitiating Cues: The Unit 2 SS directs you to determine the maximul Attachment M, Page 3.	m RCS venting time per F5 Appendix B,
ime Critical Task: YES/NO Alternate Path:	YES/ <u>NO</u>
/alidation Time: Minutes Time Started _	Time Finished:

App	endix	С

Form ES-C-1 (R8, S1)

PERFORMANCE INFORMATION	ON NC
(Denote critical steps with BOLD)	
1 Performance step: CRITICAL STEP	SAT/UNSAT
DETERMINE Containment volume at standard temperature	and pressure.
Standard:	
Evaluator Note: This value is calculated by the formula:	
Vcont = 1.32 x 106 x [492/T + 460] where T = Containment Ter	mperature in Degrees F.
Containment volume calculated to be 65128 (+1, -0) Comment:	1.1808 x 10 6 43
Comment:	conect.
CUE: When candidate asks for Containment Temperature, inf "Containment Temperature is 90 °F."	orm candidate that,
2 Performance step: CRITICAL STEP	SAT/UNSAT
DETERMINE maximum Hydrogen volume that can be vented	d.
Standard:	
Evaluator Note: This value is calculated by the formula: Vmax = where CONC = Containment Hydrogen Concentration in %.	= [(3.0-CONC) x Vcont/100%
Maximum Hydrogen volume that can be vented calculated to	o be 19 5 3 tt³
Comment:	35424 ft 3
Evaluator Cue: When candidate asks for Containment Hydroge	• • •

Evaluator Cue: When candidate asks for Containment Hydrogen concentration, inform candidate that, "Containment Hydrogen concentration is 0%."

PERFORMANCE INFORMATION	N
(Denote critical steps with BOLD)	
3 Performance step: CRITICAL STEP	SAT/UNSAT
DETERMINE Hydrogen flow rate (W) using Figure 8.	
Standard:	
Hydrogen flow rate determined to be 2900 scfm (+/-0)	
Comment:	
4 Performance step: CRITICAL STEP	
4 Performance step: CRITICAL STEP	SAT/UNSAT

CALCULATE maximum venting time.

Standard:

Evaluator Note: This value is calculated by the formula: Tmax = Vmax/W No tolerance is given on this value as it uses values already determined and their allowable tolerance on those values does not change the result of this value out to the third decimal place.

Maximum RCS venting time calculated to be .673 minutes or 40 seconds (+1-0).

(12,22 muinets)

Comment:

Terminating cue:

Candidate should inform the Unit 2 SS that, "maximum RCS venting time is 40 seconds (.673 minutes)." At this point inform the cadidate that, "this JPM is complete."

Complete
Comments
Incorporated 7/19/02
leduced the ancent-f
data to be recorded to
treduce the # of coloulations

RO OPTEST JAM A.1 6 D

N4ED (ory of 1005B

Moderal wo copy

(Loop to Oaka 15 the Same)

Facility: Prairie Island	Task No:
Task Title: Perform Alternate Calculation of RX Thermal Power	Job Performance Measure No: A.1.b
K/A Reference: 2.1.23 [3.9/4.0]	
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing:	
Simulated Performance Actual Performance _X	_ Classroom Simulator _X _ Plant
READ TO THE EXAMINEE	
I will explain the initial conditions, which steps to sin cues. When you complete the task successfully, the measure will be satisfied.	nulate or discuss, and provide initiating e objective for this job performance
Initial Conditions:	
 Unit 1 is operating. NIS inputs into the "CALM" program are OO SP-1005, " Unit 1 NIS Power Range Daily Ca 	S. alibration," is due.
Task Standard: Complete SP-1005B acurately	y.
Required Materials: Steam Tables, Calculator, Co	py of SP-1005B
General References: SP-1005B	
Initiating Cues:	
 The SS has directed you to perform SP-1005 Thermal Power," using Main Control Board d 	5B, "Unit 1 Alternate Calculation fo Reactor ata.
Time Critical Task: YES/NO Alternate Path:	YES/ <u>NO</u>
Validation Time: Minutes Time Started /	7 76 Time Finished:
ATTACH Pre filled in capies Lun use By Evaluter.	of Jubbs with Jem

Ap	per	ndix	C

Form ES-C-1 (R8, S1)

PERFORMANCE INFORMATION

(Denote cri	itical steps with BOLD)			
1Pe	rformance step: CRITIC	CALTASK	SAT/UNSA	\T
First set of	f Calorimetric data is	gathered and recorded ir	ı Table 1	
Standard:				
First set of	f data points are recor	rded onto Table 1.		
Comment:				
CUE: If as	sked, as the SS direct it examinee that 5 minute	ems 'A' to be the preferred s has elapsed.	d data source. When data is tak	(en
		TEE ATTACHED	TABLE I	
Note: PAT	2 forces from	NOTE:	EACS TURN ON COME SATIUNS	
2_ Per	formance step: CRITIC	AL STEP	SAT/UNS/	AT or
Second set	t of calorimetric data i	s gathered and recorded		7.
Standard:				
	of calorimetric data a	sheuld be	recorded & min efter	:_
Comment:		(auxilition) of	the first send duta	
CUE: None	9.			
- Cre	reconstitus			
	Power stalle	duit reporter	INC4,	
	5/6 land	N ON William	15	
	1 1 -141			

Α	n	n	e	n	d	i¥	C
_	۲.	μ	C		u	ľ	\sim

Form ES-C-1 (R8, S1)

PERFORMANCE INFORMATION	
(Denote critical steps with BOLD)	
3 Performance step: CRITICAL STEP SAT/UN	SAT
AVERAGE all inputs.	
Standard:	
Data points are averaged and recorded onto Table 1.	
Comment:	
CUE: None	
4 Performance step: CRITICAL STEP SAT/UNS	AT
CALCULATE uncorrected % full power by completing the hand calculation in table 2.	
Standard:	
Uncorrected % full power Calculated and recorded in table 2.	
Comment:	
CUE: None	

Appendix C	Form ES-C-1 (R8, S1)
PERFORMANCE INFORMATION	
(Denote critical steps with BOLD)	
5 Performance step: CRITICAL STEP CORRECT For blowdown flow	SAT/UNSAT
Standard:	
Actual % full power calculation completed.	
Comment:	

Actual full power is calculated per step 8.4

CUE: None.

Terminating cue:

Initial Conditions:

- Unit 1 is operating.
- NIS inputs into the "CALM" program are OOS.
- SP-1005, "Unit 1 NIS Power Range Daily Calibration," is due.

Initiating Cues:

The SS has directed you to perform SP-1005B, "Unit 1 Alternate Calculation fo Reactor Thermal Power," using ERSC terminal in the TSC or EOF.

Simulation of Barrel F



NUMBER:

SP 1005B

REV:

11

Page 1 of 16

FW, MS, SB	wo :
Work Order Initiated: YES NO	WO No
est Performance:	
Performed By:(Signature or Initials)	Date: ,
Additional Requirements: NONE	
Review of Acceptability: Acceptance Criteria Met? YES/NO	Shift Supervisor:
SP Completion: Shift Supervisor:	Date:
SP Surveillance Schedule Satisfied. YES/N	IO Surv. Admin:
ther Actions for Consideration:	
Nuclear Engineer Review:	Date:
O.C. REVIEW DATE: OWNER:	EFFECTIVE DATE
7/3/02 J. Kar	pitz $7/2/37$



NUMBER:

SP 1005B

REV: 11

Page 2 of 16

1.0 PURPOSE AND GENERAL DISCUSSION

for the harmon of the large

- Continuous use of procedure required.
- Read each step prior to performing.
- Mark off steps as they are completed.
- Procedure SHALL be at the work location.

1.1 Purpose

- 1.1.1 This surveillance procedure provides an alternate method of calculating reactor thermal power when the ERCS calorimetric program (CALM) is not available.
- **1.1.2** Reactor thermal power is determined by a secondary plant thermodynamic calculation.

1.2 Acceptance Criteria

1.2.1 General

In the event Acceptance Criteria cannot be met, refer to Ops. Manual Section G "Surveillance And Periodic Test Program" for additional guidance.

1.2.2 Procedure Completion

This SP is acceptable when Table 2 has been completed resulting in a reactor power level determination.

1.3 General Discussion

- 1.3.1 Steps in this procedure that are not Acceptance Criteria (not asterisked) are to be observed and inconsistencies noted. If there are significant deviations or questions as to the operability, contact the Shift Supervisor or System Engineer for guidance.
- 1.3.2 Parameters outside the Minimum or Maximum require immediate contact with the Shift Supervisor. In some cases, this may require prompt action to prevent equipment damage. Consideration should be given to aborting the procedure.



NUMBER: SP 1005B REV: 11

Page 3 of 16

- 1.3.3 Every step identified by an asterisk (*) must be acceptable for this test to be acceptable. <u>IF</u> any acceptance step is not met, <u>THEN</u> the Shift Supervisor **SHALL** be notified immediately.
- 1.3.4 Several steps of this procedure may be performed by operations personnel outside of the Control Room, with these steps identified by a "pound sign" (#).

2.0 REFERENCES

- 2.1 SP 1005, NIS Power Range Daily Calibration
- 2.3 Project 81Y181R, 87Y785, Modification Documentation
- **2.4** Flow Diagrams:
 - NF-39218, Main Auxiliary Steam & Steam Dump
 - NF-39222, Feedwater System Unit 1
 - NF-88740, Steam Generator Blowdown System Units 1 & 2
- 2.5 Implementing Reference(s)
 - C21.1.2, PROGRAMMABLE CONTROLLER SYSTEM


3.0 PRECAUTIONS AND LIMITATIONS

- 3.1 Do not use invalid or rejected ERCS points.
- 3.2 If instrument accuracy is in question, verify instrument accuracy with I&C.

4.0 PERSONNEL AND SPECIAL EQUIPMENT REQUIREMENTS

4.1 Suggested Personnel

- 4.1.1 One (1) Control Room Operator to record data and make calculations.
- 4.1.2 One (1) Outplant Operator to take data.
- 4.1.3 One (1) Instrumentation & Control Technician to take data.



NUMBER:		
S	P 10	005B
RI	EV:	11

Page 4 of 16

4.2 Special	l Equipment
-------------	-------------

Calibrated Digital Volt Meter (DVM)	
PI Number	Calibration Due Date:

5.0 SPECIAL CONSIDERATIONS

NONE

6.0 PREREQUISITES AND INITIAL CONDITIONS

- **6.1** Power greater than 15% rated thermal power.
- **6.2** $T_{AVG} = T_{REF} \pm 0.5^{\circ}F$ except in coastdown operations per C1.4.
- **6.3** Power as measured by NIS is stable, $\pm 1\%$.
- 6.4 SG level is on program $\pm 4\%$.



NUMBER:

SP 1005B

REV:

Page 5 of 16

11

7.0 PROCEDURE

7.1 Record the Parameter sources and values for the FIRST SET of data in Table 1. N/A portions of table that are not used.

est



Each calorimetric parameter has several potential sources for the required data. Parameter sources are sequentially listed by preference, but the Shift Supervisor may select any of the listed sources. Record the selected data in Table 1. The data points not used should be marked NA.



ERCS Turn-On-Code (TOC) GRPDIS, Group (SP1005B), may be used to obtain values for some of the ERCS points.

7.2 Steam Generator Pressure

7.2.1 11 Steam Generator

A. ERCS:

1660

1U2015A, STEAM GENERATOR A AVERAGE PRESS

1P0400A, LOOP A STM GEN PRESS 468

1P0401A, LOOP A STM GEN PRESS 469

1P0402A, LOOP A STM GEN PRESS 482

B. Main Control Board Pressure Recorder 1PR-468 (42068):

NA

CH1: 1P-468

CH2: 1P-469

CH3: 1P-482

C. Main Control Board Pressure Indicators:

NIN

1PI-468 (4113701)

1PI-469 (4113702)

1PI-482A (4113703)



NUMBER:

SP 1005B

REV:

11

Page 6 of 16

NI

D. HSD panel (51000) Pressure Indication:

1PI-482B (11710), STM GEN MN STM HDR PI

7.2.2 12 Steam Generator

A. ERCS:

M

1U2016A, STEAM GENERATOR B AVERAGE PRESS

1P0420A, LOOP B STM GEN PRESS 478

1P0421A, LOOP B STM GEN PRESS 479

1P0422A, LOOP B STM GEN PRESS 483

B. Main Control Board Pressure Recorder:

NUI

1PR-478 (42069)

CH1: 1P-478

CH2: 1P-479

CH3: 1P-483

C. Main Control Board Pressure Indicators:

N/A

1PI-478 (4113801)

1PI-479 (4113802)

1PI-483A (4113803)

D. HSD panel (51000) Pressure Indication:

NA

1PI-483B (11711), STM GEN MN STM HDR PI



NUMBER:

SP 1005B

REV:

Page 7 of 16

11

7.3 Feedwater Temperature

I&C personnel support will be required for data retrieval.

7.3.1 11 SG FW Inlet Temperature

A. ERCS:

il

1T0418A, LOOP A STM GEN FW TEMP

1U2011A, STEAM GENERATOR A FEEDWATER TEMP

B. Send I&C Tech to retrieve Digital Volt Meter (DVM) test point data from 1FW rack (TP/TQ498 LOOP A FW TEMP) and report the data to Operations.

NA

Convert DVM data to temperature using the following calculation:

Temperature (°F) =
$$(DVM data - 0.1)$$
 X 500°F 0.4

DVM

۰F

First Set

Loop A _ N/A

N/st

Second Set

Loop A

NA

I&C Engineering SHOULD be contacted prior to using the common RTD reading. The accuracy of this reading may need engineering review.

C. Request I&C obtain the common FW Line Temperature from RTD-TE-15255, 11/12 SG FW Hdr RTD.

NA



NUMBER:

SP 1005B

REV:

11

Page 8 of 16



I&C personnel support will be required for data retrieval.

7.3.2 12 SG FW Inlet Temperature

A. ERCS:

jest

1T0438A, LOOP B STM GEN FW TEMP

1U2012A, STEAM GENERATOR B FEEDWATER TEMP

B. Send I&C Tech to retrieve Digital Volt Meter (DVM) test point data from 1FW rack (TP/TQ499 LOOP B FW TEMP) and report the data to Operations.

NIT

Convert DVM data to temperature using the following calculation:

Temperature (°F) = (DVM data - 0.1) X 500°F 0.4

DVM

٥F

First Set

Loop B

NA

NA

Second Set Loop B

1/1

NA

i&C Engineering SHOULD be contacted prior to using the common RTD reading. The accuracy of this reading may need engineering review.

C. Request I&C obtain the common FW Line Temperature from RTD-TE-15255, 11/12 SG FW Hdr RTD.

NA



NUMBER:

SP 1005B

REV:

11

Page 9 of 16

7.4 Feedwater Flow



Variance in Feedwater Flow has the greatest effect on calorimetric Reactor Thermal Power.

7.4.1 11 SG Feedwater Flow

A. ERCS:



If 1U2028A is used, insert this value directly in Table 2 at step B7 and NA steps B1 thru B6 of Table 2.

1. 1U2028A (MLB/HR)

; 587

- 2. 1F2511A (SQRTIN)
- 3. 1AFWAV (SQRTIN) 5 minute average
- B. Notify I&C to retrieve DVM test point data from 1FW rack (TP/FQ495 LOOP A FW FLOW) and report the data to Operations.



Record DVM readings, then convert to square-rootextracted inches of water for use in the calculation.

$$\sqrt{IN} \text{ H}_2\text{O} = \frac{(\text{DVM reading} - 0.1)}{0.4} \times 19.35 \sqrt{IN} \text{ H}_2\text{O}$$

DVM

Flow

First Set

Loop A

• •

Second Set Loop A

- N/K

<u>IF</u> the feedwater flow transmitter is not available, <u>THEN</u> complete Step 7.4.1.C Other times, this step may be NA'ed.

C. Notify I&C to install a calibrated DP Barton indicator (connect Barton at tap set 2 for Loop A) that reads in inches of water and report the data to Operations.

w/A



NUMBER:

SP 1005B

REV:

': 11

Page 10 of 16

7.4.2 12 SG Feedwater Flow

A. ERCS:





If 1U2029A is used, insert this value directly in Table 2 at step B7 and N/A steps B1 thru B6 of Table 2.

- 1. 1U2029A (MLB/HR) 3.5-82.
- 2. 1F2512A (SQRTIN)
- 3. 1BFWAV (SQRTIN) 5 minute average
- B. Notify I&C to retrieve DVM test point data from 1FW rack (TP/FQ497 LOOP B FW FLOW) and report the data to Operations.



Record DVM readings, then convert to square-root-extracted inches of water for use in the calculation.

$$\sqrt{IN} H_2O = \frac{\text{(DVM reading} - 0.1)}{0.4} \times 19.28 \sqrt{IN} H_2O$$

DVM

Flow

First Set

Second Set

Loop B

Not

N/A

IF the feedwater flow transmitter is not available, <u>THEN</u> complete step 7.4.2. C. Other times, this step may be NA'ed.

Loop B

C. Notify I&C to install a calibrated DP Barton indicator (connect Barton at tap set 1 for Loop B) that reads in inches of water and report the data to Operations.

NA



7.10

ALTERNATE CALCULATION OF REACTOR THERMAL POWER

NUMBER:

SP 1005B

REV:

Page 11 of 16

11

7.5 Steam Generator Blowdown Flow

	27/2		For Graphic Display - Notify Aux Building Operator to retrieve SG Blowdown Flow using the 1SGB Program in the Programmable Controller System (PCS) per C21.1.2.	
	7.5.1	11	SGB Flow	
		A.	ERCS - 1U2017A, STEAM GENERATOR A BLOWDOWN FLOW.	_ /K
		В.	Panel 58350, SGB; WL; ARTD SYSTEMS GRAPHIC DISPLAY SYSTEM.	NI
		C.	Local Flow Indication - FI-58101, 11 SGB FI.	NA
	7.5.2	12	SGB Flow	
		A.	ERCS - 1U2018A, STEAM GENERATOR B BLOWDOWN FLOW.	M
		B.	Panel 58350, SGB; WL; ARTD SYSTEMS GRAPHIC DISPLAY SYSTEM.	what
		C.	Local Flow Indication - FI-58102, 12 SGB FI.	wlat
7.6	Five (5) sources in Table	s as i	utes after the initial data was recorded, using the same dentified in Step 7.1, record the SECOND SET of data	ell
7.7	Comple	ete the	e Average column.	jul
7.8	Use Tal	ble 1 ling T	Average Data and calculate the % full power by able 2.	ich
7.9	Calculat	ea pe	lure (SP 1005B) was initiated by SP 1005, record the ercent reactor thermal power as the Average Reactor ver in Table 1 of SP 1005. Otherwise, this step is	

Attach this SP (SP 1005B) to the initiating procedure.



NUMBER:
SP 1005B
REV: 11
Page 12 of 16

8.0 ADDITIONAL REQUIREMENTS

NONE

9.0 ATTACHMENTS

- 9.1 Table 1 Calorimetric Input Data
- 9.2 Table 2 Hand Calculation Sheet.
- 9.3 Figure 1 Thermal Expansion Factor 304 Stainless Steel Nozzles.



NUMBER:

SP 1005B


REV:

11

Page 13 of 16

Table 1 Calorimetric Input Data

PARAMETER	SOURCE	FIRST SET	SECOND SET	AVERAGE
TIME	N/A	10281,040	1645	N/A
	LOG	OP A		
11 Steam Generator Pressure (psig)	ERCS 147015A	709.4	709.4	789.4
11 Feedwater Temperature (°F)	ERCS 142011A	432.3	472.3	432.3
11 Feedwater Flow √in H₂O	ERCS 1F251/A 5RCS	15.567	15.567	15.567
11 Steam Gen Blowdown Flow (gpm)	5 RCS	59.1	59.1	59.1
	LOO	P B		
12 Steam Generator Pressure (psig)	142016A	709.5	709.5	701.5
12 Feedwater Temperature (°F)	EK(S	432.3	432.3	432.3
12 Feedwater Flow √in H₂O	1470,2A (KCS 11-2512A	15.482	15:482	15.482
12 Steam Gen Blowdown Flow (gpm)	142018A	41.7	41.7	41.7



NUMBER: SP 1005B

REV:

Page 14 of 16

11

Table 2 Hand Calculation Sheet

A. STEAM GENERATOR ENTHALPY CHANGE

1. Steam Pressure (psig)

+14.7

Steam Pressure (PSIA)

- 2. Corresponding Enthalpy (h_g) BTU/lb (Use Steam Tables)
- 3. Feedwater Temperature (°F)
- 4. Corresponding Enthalpy (h_f) BTU/lb (Use Steam Tables)
- 5. Enthalpy Difference (A2 A4) BTU/lb

LOOP A	_	LOOP B	
709.4		709,5	
+14.7		+14.7	
724.1	LOOP A	724.2	LOOP B
	1201.27		1201.27

432.3		432.3	
	410.40		410.49

790.8	3	7 90.9
	1	J L 6


B. <u>FEEDWATER FLOW</u>


- 1. Flow ($\sqrt{\text{in}} H_2O$)
- 2. Fa (from Figure 1)
- 3. Flow Constant
- 4. B1 (X) B2 (X) B3 =
- 5. Feedwater Specific Volume @ Temp A3, (Use Steam Tables)

6.
$$\sqrt{V_f} = \sqrt{B5}$$

7. $m(feedflow in 10^6 lb/hr) = (B4) + (B6)$

15.567	
1.0169	
0.03161	
0.49547	
0.019134	ワ





NUMBER: SP 1005B REV: 11

Page 15 of 16

Table 2 Hand Calculation Sheet

C.	POWER	î v
	r	4. LOOP B
1.	A5 (X) B7 = Loop Thermal Power 790.87	2836.71 2832.75
2.	Loop A (+) Loop B = Total Thermal Power	5669.46
	Minus 24 (RCP thermal input)	-24.0
3.	Total Thermal Power in 10 ⁶ BTU\hr	5646.46
	(X) 0.2929	X 0.2929
4.	Total Thermal Power in Megawatts	165356
	(X) 0.06061	X0.06061
5.	% Full Power (uncorrected for steam generator blowde	own) 100.22

FP = Full Power corrected for SG blowdown
FPuc = Full Power uncorrected for blowdown
SGA = SG "A" Blowdown Flow in gpm
SGB = SG "B" Blowdown Flow in gpm

* 6. % Full Power (corrected for steam gen. blowdown)

FP = (FPuc) -
$$\left[\frac{(SGA + SGB) - 20}{200}\right]$$

FP = $\left(\frac{10^{0.11}}{200}\right)$ - $\left[\frac{(59) + 4^{0.7} - 20}{200}\right]$
FP = $\frac{99.52}{8}$ Full Power




NUMBER:

SP 1005B

REV: 11

Page 16 of 16

Figure 1 Thermal Expansion Factor 304 Stainless Steel Nozzles



Abstracted from Nozzle Vendors Manual W-1014, Section 9.

Job Performance Measure Worksheet

Form ES-C-1 (R8, S1)

Facility: Prairie Island	Task No:
Task Title: Prepare an Isolation for 11 TD AFW Pump	Job Performance Measure No: RO A.2
K/A Reference: <u>2.2.13, 2.1.24 [3.1/3.3, 2.8/3.1]</u>	
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing: Simulated Performance X Actual Performance	Classroom _X Simulator Plant
READ TO THE EXAMINEE	
I will explain the initial conditions, which steps to scues. When you complete the task successfully, measure will be satisfied. Initial Conditions: Unit 1 is at 100 % power While running the 11 TD AFWP for surveil casing for the pump, and there was exces The 11 TD AFWP was just shutdown and	llance, a steam leak developed on the turbine sive water leakage on the inboard pump seal
and the water side of the 1 Required Materials: Flow Diagrams: NF-392 C28-2, "Auxiliary Feedw B Section Figures B27- C28-2, "Auxiliary Feedw C28-2, "Auxiliary Feedw	water System Unit 1" 216-2, NF-39218, and NF-39222 01, B28B-1, and B28B-2 water System Unit 1"
Initiating Cues: The Shift Supervisor directs you to IDENT mechanically isolate the 11 TD AFWP on DOCUMENT using the form provided.	TIFY the components and their positions to the steam side and on the water side.
performed <u>at a later time</u> through Work C	Control which will include an electrical isolation
 At the present time we just need to mech 	anically isolate the steam side and water side atrol requests the tag section for the pump. IDENTIFY THE VERY OF A MICHAEL PARTIES AND TOPNITH TO AFTER VERY VERY TOWN TOWN TOWN TOWN TOWN TOWN TOWN TOWN
Time Critical Task: YES/NO Alternate Pa	d Time Finished: tonewh
CHAMPS IS NOTED THE EGMANS	Concer. Changes incorporated Continuements). Continuements).

Appendix C	2	Form ES-C-1 (R8, S1)
	PERFORMANCE INFO	ORMATION
(Denote critical steps with B	OLD)	
1Performance step:	CRITICAL STEP	SAT/UNSAT
IDENTIFY steam supply to	the 11 TD AFWP is to b	e isolated.
Standard:		
IDENTIFY steam supply to following on the form prov	the 11 TD AFWP is to be	e isolated by documenting the
CLOSE MV-32016, "11 MAII CLOSE MV-32017, "12 MAII OR	N STM TO 11 TD AFWP' N STM TO 11 TD AFWP'	" using control switch CS-46127 " using control switch CS-46128
	overspeed trip valve CV	-31059, "TRIP / THROTTLE VALVE TO
Comment:		

		 	
		PERFORMANCE INFO	DRMATION
(Deno	te critical steps with I	BOLD)	
2	_ Performance step:	CRITICAL STEP	SAT/UNSAT
IDENT	TFY discharge of th	e 11 TD AFWP is to be is	olated.
Standa	ard:		
	TIFY discharge of the form provided:	e 11 TD AFWP is to be is	olated by documenting the following
Locall OR	y CLOSE the 11 TD	AFWP manual discharge	valve AF-13-3 "11 AFWP DISCHARGE
CLOS CLOS	E MV-32238, "11 TD E MV-32239, "11 TD	AFWP TO 11 STM GEN" AFWP TO 12 STM GEN"	using control switch CS-46314 using control switch CS-46315
Locall	y CLOSE AF-17-1 "	I1 AFWP TEST LINE ISOI I1 AFWP RECIRC / LUBE	ATION"
EVALI	JATOR NOTES:		
_		d and still accomplish th	r arrangements of valves may be e required mechanical isolation of the
	Other selection of		required isolation of the discharge of se-by-case basis
Comm	ent:		

r enomance step.	CRITICAL STEP	SAT/UNSAT
DENTIFY suction of the 1	1 TD AFWP is to be isolated.	
Standard:		
DENTIFY suction of the 1 he form provided:	1 TD AFWP is to be isolated by o	documenting the following on
CLOSE MV-32333 "COND		
CENTER CLUSED MV-3202	TO 11 TD AFWP SUCT" using c 5, "CLG WTR TO 11 TD AFWP S	ontrol switch CS-46420 UCT" using control switch
S-46433	FO 11 TD AFWP SUCT" using c. 25, "CLG WTR TO 11 TD AFWP S	UCT" using control switch
S-46433	5, "CLG WTR TO 11 TD AFWP S	UCT" using control switch

Concar. Comments incorporated
Mullar

Α	ndix C
Α	ndıx (

5

Form ES-C-1 (R8, S1)

VERIFICATION OF COMPLETION
Job Performance Measure No
Examinee's Name:
Examiner's Name:
Date performed:
Facility Evaluator:
Number of attempts:
Time to complete:
Question Documentation:
Question:
Response:
Result: SAT or UNSAT
Examiner's signature and date:

্রমSOLATION FOR THE 11 TD AFWP

Concorrent.
Incorporated.
Malos

Component ID	Component Description	Isolation Status
CS-46127*	11 MAIN STM TO 11 TD AFWP MV-32016	CLOSED
.CS-46128*	12 MAIN STM TO 11 TD AFWP MV-32017	CLOSED
CV-31059*******	TRIP / THROTTLE VALVE TO 11 TD AFWP	CLOSED/TRIPPED
AF-13-3+	11 AFWP DISCHARGE	CLOSED
CS-48314++	11 TD AFWP TO 11 STM GEN MV-32238	CLOSED
. C8-463 15++	11 TD AFWP TO 12 STM GEN MV-32239	CLOSED
AF-17-1++	11 AFWP TEST LINE ISOLATION	CLOSED
AF-18-1++	11 AFWP RECIRC / LUBE OIL COOLING	CLOSED
M V 32 3'5'5		
CS-46420	COND TO 11 TD AFWP SUCT MV-32333	CLOSED
CS-46433	CLG WTR TO 11 TD AFWP SUCT MV-32025	CLOSED
CL-113-1 ##	CLG WIR IJOLATION! TO 11 AFWP	CLOSED
	1	
EVALUATOR NOTES	S: Ruchion school be 11 10 At wip.	

EVALUATOR NOTES:

Either the valves identified by an asterisk (*) OR the valves identified by a double asterisk (**) must be closed

Either the valves identified by a plus (+) OR the valves identified by a double plus (++) must be closed

There is some latitude allowed, in that other arrangements of valves may be selected and closed and still accomplish the required mechanical isolation of the steam side and the water side of the 11 TD AFWP

Other selection of valves to accomplish the required isolation of the 11 TD AFWP must be evaluated on a case-by-case basis

- Enther the volve identified by a pound sign (#) OR the value identified by a double paind sign (##) must be closed

Since mental vilve or Could be used for idelesses

Initial Conditions:

Unit 1 is at 100 % power

While running the 11 TD AFWP for surveillance,

a steam leak developed on the turbine casing for the pump, and there was excessive water leakage on the inboard pump seal

The 11 TD AFWP was just shutdown and declared (oncernage and miletos

inoperable

Initiating Cues:

The Shift Supervisor directs you to IDENTIFY the -components and their positions to isolate the 11 TD AFWP on the steam side and on the water side.

DOCUMENT using the form provided.

A tag section per 5AWI 15.5.1, "Plant Equipment Control and Clearance Process" will be performed at a later time through Work Control which will include an electrical isolation of the appropriate components.

At the present time we just need to mechanically isolate the steam side and water side leaks on the 11 TD AFWP until Work Control requests the tag section for the

pump. the Shift Spervisor just needs you to IDFNTIFY the values and their positions required to provide a machinical isolation boundary for the 11 TD AFWP. These values will later be put on the lay section to be wither for the pump.

ISOLATION FOR THE 11 TD AFWP

Component ID	Component Description	Isolation Status
		isolation Status
		
		
<u></u>		1

Appendix C		Job Performan Worksh		, ,
Facility: Prairie I	sland		Task No:	
	ew an Isolation for p and Determine LCOs will Resul	if any Tech	Job Perform	ance Measure No: <u>SRO A.2</u>
K/A Reference:	<u>2.2.13, 2.1.24 [3</u>	.1/3.3, 2.8/3.1]		
Examinee:			NRC Examin	ner:
Facility Evaluator:			Date:	
Method of testing	<u>:</u>			
Simulated Perforr	nance <u>X</u> Actua	al Performance	Classroom	X Simulator Plant _
cues. When you measure will be some some some some some some some som	complete the tas atisfied. <u>s:</u>	k successfully, t	he objective fo	uss, and provide initiating or this job performance on day 2 of 7 day clock),
•	t 100% power, N	O Tech Spec LO	Os in effect	
Task Standard:	allow the 11 TD Section for the 1	AFWP to be taken 1 TD AFWP to	ken OOS, and be released fo	cal Specifications will NOT thus NOT approve the Tag r isolation.
Required Material	 Work We PRA risk Flow Dia C28-2, "// 	eek Schedule sl profile with Die	nowing 11 TD . sel Generator 16-2, NF-3921 ater System U	8, and NF-39222
General Referenc	B Section	grams: NF-392° n Figures B27-0	1, B28B-1, and	d B28B-2

4. Technical Specifications

Replaced JPM with another JTM

Replaced JPM with another JTM

to perform a Risk Assessment because

to perform a Risk Assessment because

It TO Afuip energent work, because

the II TO Afuip would not be

the II TO Afuip would not be

taken OCS under JPM.

specified in this JPM.

Alabor

Concern.

Αp	ne	nc	lix	\mathbf{C}
$\neg \nu$	\sim	110	41 A	\sim

Job Performance Measure Worksheet

Form ES-C-1 (R8, S1)

Facility:	Prairie Island	Task No:
i aciiity.	T Taille Island	I ASK INU.

Task Title: Review an Isolation for 11 TD AFW Job Performance Measure No: SRO A.2

Pump and Determine if any Tech

Spec LCOs will Result

K/A Reference: 2.2.13, 2.1.24 [3.1/3.3, 2.8/3.1]

Initiating Cues:

- A Tag Section was brought to you for approval to take OOS the 11 TD AFWP.
- A copy of the Work Week Schedule is attached.
- The PRA risk profile with Diesel Generator D2 OOS is also attached.
- You are being requested to review and approve the Tag Section for the 11 TD AFWP and release it for isolation.
- You also need to EVALUATE what (if any) Technical Specifications would be associated with the OOS of the 11 TD AFWP.

Time Critical Task:	YES/ <u>NO</u>	Alternate Path: YES/NO	
Validation Time:	Minutes	Time Started	Time Finished:

Appendix C	3	Form ES-C-1 (R8, S1)
	PERFORMANCE INFOR	RMATION
(Denote critical steps with E	OLD)	
	CRITICAL STEP	SAT/UNSAT
EVALUATE and do NOT a_{\parallel} isolation.	oprove the Tag Section for	r the 11 TD AFWP to be released for
Standard:		
RECOGNIZES that the Ris 11 TD AFWP to be taken C 11 TD AFWP to be release	OS, and thus does NOT a	pecifications will NOT allow the pprove the Tag Section for the
Comment:		
2_ Performance step:	SAT/U	NSAT
EVALUATE the Tag Section	for the 11 TD AFWP for ac	curacy.
Standard:		
IDENTIFIES that the Tag Se	ection for the 11 TD AFWP i	s accurate.

Comment:

	PERFORMANCE	INFORMATION
(Denote critical steps with B	OLD)	
3 Performance step:	CRITICAL STEP	SAT/UNSAT
EVALUATE affected Tech	Specs for the inope	rability of the 11 TD AFWP.
Standard:		
 DETERMINE that Di 12 MD AFWP DETERMINE based Section 1.0 of Tech the 11 TD AFWP we DETERMINE that Te required within one 	on the DEFINITION Specs that the 12 Notes that t	nade inoperable that Tech Spec 3.4.B apply is the emergency power source for the of "OPERABLE - OPERABILITY" in MD AFWP would also become inoperable is led then apply and that action would be cing Unit 1 in HOT SHUTDOWN within the ge temperature below 350°F within the
Comment:		
Terminating cue:	·	

Λ	_	De	•			
n	v	υŧ	:11	u	IX.	L

Form ES-C-1 (R8, S1)

VERIFICATION OF COMPLETION
Job Performance Measure No
Examinee's Name:
Examiner's Name:
Date performed:
Facility Evaluator:
Number of attempts:
Time to complete:
Question Documentation:
Question:
Response:
Result: SAT or UNSAT
Examiner's signature and date:

Initial Conditions:

- Unit 1 is at 100 % power, Diesel Generator D2 is OOS (on day 2 of 7 day clock), 11 Charging Pump is OOS
- Unit 2 is at 100% power, NO Tech Spec LCOs in effect

Initiating Cues:

- A Tag Section was brought to you for approval to take
 OOS the 11 TD AFWP.
- A copy of the Work Week Schedule is attached.
- The PRA risk profile with Diesel Generator D2 OOS is also attached.
- You are being requested to review and approve the Tag Section for the 11 TD AFWP and release it for isolation.
- You also need to EVALUATE what (if any) Technical Specifications would be associated with the OOS of the 11 TD AFWP.

Completel
Charges neorproduct
7/15/02
Connocts wode by
Chief Examine

RO OF TEST JPM 4.3 0

Mared os versión Procedure atteched

Appendix C	Job Performance Measure Form ES-C-1 (R8, S1 Worksheet
Facility: Prairie Island	Task No:
Task Title: Preparations for emer containment entry	Job Performance Measure No: ROA.3
K/A Reference: _2.3.10 [2.9/3.3]	
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing:	
Simulated Performance _X_ Actu	al Performance Classroom _X_ Simulator Plant
READ TO THE EXAMINEE	
 cues. When you complete the tas measure will be satisfied. Initial Conditions: Unit 1 is at 25% during sta A 2.0 gpm RCS leak has be surveillance. It is suspected that RC-1-1 R-11 and R-12 are alarmin A team is being assembled in A Loop RCP vault) Conditions: Task Standard: At least 8 re with R-11 are 	and RC-1-2 are leaking by their seats into the RCDT gon-scale. — he beld to enter containment to attempt isolation of the leak (located during 15 92" quirements identified for an emergency containment entry d R-12 alarming on scale.
	on Safety," Rev.20. SAFETY MANJAL
General References: F-2, "Radiati	on Safety," Rev.20.
Initiating Cues:	

- The SM has directed you to prepare for an emergency containment entry per F-2. You are to **list** all requirements that must be met prior to containment entry.

Validation Time:	Minutes	Time Started	Time Sinish aut
Validation Time	Minutes	Time Started	Time Finished:

Ap	pei	ndi	x C

Form ES-C-1 (R8, S1)

PERFORMANCE INFORMATION
(Denote critical steps with BOLD)
1_ Performance step: SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.3.2
Standard:
Candidate finds and reads F-2, "Radiation Safety," Rev.20. Step 9.3.2, "Emergency Entry is defined as non-routine entry for inspection or operation such as a fire alarm or limit switch position check."
Comment:
CUE: If asked provide the candidate a copy of F-2, "Radiation Safety," Rev.20.

All stell

I may note regist of no entry diving sty
ifen 9.1,2

cue: startup secured. No reactivity changes.

(Denote	critical	steps	with	BOL	D)
---------	----------	-------	------	-----	----

2 Performance step: CRITICAL STEP

SAT/UNSAT

F-2, "Radiation Safety," Rev.20. Step 9.2

Specific requirements for containment entry while at hot standby and power are spelled out in these procedures.

F-2, "Radiation Safety," Rev.20. Step 9.2.1, The entry team SHALL be equipped with dosimeters, TLD's, and a beta-gamma survey instrument.

Standard:

Candidate determines that this requirement applies and documents by listing on the sheet provided.

Comment:

CUE: None

3 Performance step: CRITICAL STEP

SAT/UNSAT

F-2, "Radiation Safety," Rev.20. Step 9.2.2, Entry into the RC loops and Reactor Cavity SHALL NOT be permitted without permission from the superintendent of Radiation Protection and Chemistry or his designee.

Standard:

Candidate determines that this requirement applies and documents by listing on the sheet provided.

Comment:

CUE: None.

(Denote critical steps with BOLD)
4_ Performance step: SAT/UNSAT
 F-2, "Radiation Safety," Rev.20. Step 9.2.3, Prior to containment entry, contact the Shift Supervisor to confirm the following: A. There is not flux mapping or incore detector movement in progress. Very high radiation dose rates and possible overexposures can be eaused by the incore detectors. B. The Shield building ventilation systems are secured. C. Both the personnel and the maintenance airlocks are unlocked. Standard: Candidate determines that this requirement applies and documents by listing on the sheet provided. Comment: CUE: None.
5_ Performance step: SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.2.4, It the unit is above cold shutdown, one shield building door at each entry SHALL be closed at all times.
Standard:
Candidate determines that this requirement applies and documents by listing on the sheet provided.
Comment:
CUE: None.

(Denote critical steps with BOLD)
6_ Performance step: SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.2.5, Before entry, a pre-job briefing SHALL be conducted with those entering and Control Room personnel, as appropriate. This pre-job briefing SHALL include a discussion of all tour/work locations and anticipated radiation levels (PINGP 1112)
Standard:
Candidate determines that this requirement applies and documents by listing on the sheet provided.
Comment:
CUE: None.
7 Performance step: SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel entering the containment SHALL check in with the Control Room, or the designated person at the airlock, if posted.
When contacting Control Room prior to Containment entry at power, ensure all, personnel are wearing a TLD and Electronic Dosimeter (ED) and the ED is turned on (number and mRem indicated with the window).
Standard:
Candidate determines that this requirement applies and documents by listing on the sheet provided.
Comment:
CUE: None.

(Denote critical steps with BOLD)	
8_ Performance step:	SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.2.7, All personnel should use temperatures are above 85 degrees. The guidelines for heat stress in Manual should be reviewed. Backup teams and stay times may be re-	n the NSP PINGP Safety
Standard:	
Candidate determines that this requirement applies and documents by provided. Comment: (Suffy manual) CUE: None. Must note that the conditions	y listing on the sheet
CUE: None. Wust note that the could	tur (5) 88
9 Performance step:	SAT/UNSAT
F-2, "Radiation Safety," Rev.20. Step 9.2.8, When all personnel are or personnel and maintenance airlock hatches SHALL be locked.	ut of the containment, the
Standard:	
Candidate determines that this requirement applies and documents by provided.	
Comment: Ausis not a regunt the court with	ng

	(Denote critical steps with BOLD)		
	10 Performance step:		SAT/UNSAT
/	F-2, "Radiation Safety," Rev.20. Slep 9.2.7, All personne temperatures are above 85 degrees. The guidelines for Manual should be reviewed. Backup teams and stay times. Standard:	hast stress in the	MICH DINICH Colon.
	Candidate determines that this requirement applies and provided. Comment:	documents by list	ting on the sheet
	CUE: None.		
	rendifiance step:		SAT/UNSAT
/	F-2, "Radiation Safety," Flev.20. Step 9.2.8, When all per personnel and maintenance airlock hatches SHALL be id	rsonnel are out of ocked.	the containment, the
	Standard:		
	Candidate determines that this requirement applies and opprovided.	documents by list	ing on the sheet
	CUE: None.		

(Den	note critical steps with BOLD)	
1	Performance step: CRITICAL STEP	SAT/UNSAT
F-2, are:	"Radiation Safety," Rev.20. Step 9.3.2, B. If R-11 and R-12 of the	ne appropriate Unit
1.	Not alarming and normal readings, entry may be made without a protection.	ny respiratory
2.	Alarming on scale, entry may be made with the use of a MSA	Ultralite II.
3.	Alarming off scale, no entry may be made without the Supt. Rad appraisal and approval.	Protection or designee
Stand	dard:	
Cano shee	didate determines that this requirement (3) applies and docume t provided.	ents by listing on the
Comi	ment:	
CUE:	: If asked inform the candidate that R11 and R 12 are alarming ON s	scale.
	· · · · · · · · · · · · · · · · · · ·	
1;	Performance step:	SAT/UNSAT
F-2, " Perm	'Radiation Safety," Rev.20. Step 9.3.2, observe the requirements of it.	the Radiation Work
Stand	dard:	
Candi provid	idate determines that this requirement applies and documents by lis	iting on the sheet
Comn	ment:	
CUE:	None.	
Termi	nating cue: When the candidate determines that all F-2 requirement	ts are listed

-		_		_	
A	ממ	er	ndi	X	\mathbf{C}

Form ES-C-1 (R8, S1)

VERIFICATION OF COMPLETION
Job Performance Measure No
Examinee's Name:
Examiner's Name:
Date performed:
Facility Evaluator:
Number of attempts:
Time to complete:
Question Documentation:
Question:
Response:
Result: SAT or UNSAT
Examiner's signature and date:

Initial Conditions:

- Unit 1 is at 25% during startup.
- A 2.0 gpm RCS leak has been detected during the performance of the daily leak rate surveillance.
- It is suspected that RC-1-1 and RC-1-2 are leaking by their seats into the RCDT
- R-11 and R-12 are alarming on-scale.
- A team is being assembled to enter containment to attempt isolation of the leak (located in A Loop RCP vault)

 Contained General Area Temp is noted to be 82 F

Initiating Cues:

- The SM has directed you to prepare for an emergency containment entry per F-2.
- You are to list all requirements that must be met prior to containment entry.

Requirements
7.1.2 No Rowel Change while is cont.
9.2 1 TLD's dinsidement
9.2.2 NO RC LOOP OR Carity ENTRY Who Approved of Super RPAC.
7.2.3 NO FLUX MAP & Shield Blds went is secured.
9.2.4 one dock to Shald Bid closed
9.2.5 PRE Job 3Dief.
926 Ale Persons checkin w/ Control Room & ensure dosinerly
9.27 HEAT STEESS CONCERNS FICE VESTS & BOOK UP TEAM + STEY TIMES APPLY
9.2 & lock doors alter exit
92.9 Post Job
230 B. 2 - MAA VIHRALITE II REQUIRED
9.3.2 6 Obscare Ruf Requirements - Full Suit of Rubbil Suit.

Charges recumeded by
Examiners

SROCFIEST A.3

Monderl Versin

NEED & 5 APPENDIX A RB

Facility: Prairie Islan	nd		Task No:		
Task Title: Recognize and make preparations for emergency containment entry		Job Performance Measure No: _A.3_		<u>A.3</u>	
K/A Reference: 2.3	3.10 [2.9/3.3]				
Examinee:			NRC Examin	er:	·
Facility Evaluator: _			Date:		
Method of testing:					
Simulated Performan	nce _X_ Actual	Performance _	_ Classroom _	X Simulator P	lant
READ TO THE EXAM	MINEE				
I will explain the initia cues. When you con measure will be satis	nplete the task	hich steps to sir successfully, th	mulate or discr ne objective fo	uss, and provide initi r this job performand	ating ce
Initial Conditions:					
Unit 1 is operaAn alarm on F		Panel FP121 in	dicates there i	s a fire in Zone 20.	
Task Standard:	list of all the re	e need for an er equirements for ming off scale.	mergency con a emergency	tainment entry and p containment entry w	orepare a vith R-11
Required Materials:	F-2, "Radiatio		20. F5	appendix	A R
General References:	F-2, "Radiation	n Safety," Rev.:	20. 75	appudix	A R8
Initiating Cues:		resid	netion,	dactions	
- The SM has d brigade acces	irected you to I s to the affecte	ist all the/requir		nust be met to allow	
Time Critical Task: Y	ES/ <u>NO</u>	Alternate Path	: YES/ <u>NO</u>		
Validation Time:	Minutes	Time Started		Time Finished:	

Appendix (С
------------	---

2

Form ES-C-1 (R8, S1)

	PERFORMANO	CE INFORMATION	
(Deno	ete critical steps with BOLD)		
1	_ Performance step:	30	SAT/UNSAT
DETE	RMINE what is impacted by a fire in Zon		
Stand	ard:	20	
Evalu	ators Note: Candidate may already kno	_ `	containment.
Revie	w F5 Appendix A to determine that Zone	is the Unit 1 containmer	nt building.
Comm	nent:	20	
CUE:	If asked provide the candidate a copy of	of F5 Appendix A, Rev.8	
•			
		·	
2	_ Performance step:		SAT/UNSAT
DETE	RMINE that an emergency containment	entry is necessary for conta	inment access.
Standa	ard:	·	
Candid define	date finds and reads F-2, "Radiation Safe d as non-routine entry for inspection or o	ety," Rev.20. Step 9.3.2, "E peration such as a fire alar	mergency Entry is m"
Comm	ent:		
CUE:	If asked provide the candidate a copy o		

(Denote critical steps with BOLD)	
3 Performance step: CRITICAL STEP	SAT/UNSA
F-2, "Radiation Safety," Rev.20. Step 9.2	
Specific requirements for containment entry while at hot standby a out in these procedures.	nd power are spelled
F/2, "Radiation Safety," Rev.20. Step 9.2.1, The entry team SHALL to dosimeters, TLD's, and a beta-gamma survey instrument.	e equipped with
Standard:	
Candidate determines that this requirement applies and documents sheet provided.	s by listing on the
Comment:	
CUE: None	
Performance step: CRITICAL STEP F-2, "Radiation Safety," Rev.20. Step 9.2.2, Entry into the RC loops SHALL NOT be permitted without permission from the superintender Protection and Chemistry or his designee.	and Reactor Cavity
Standard:	
Candidate determines that this requirement applies and documents sheet provided.	by listing on the
Comment:	
CUE: None.	

5 Performance step:	SAT/UNS
F-2, "Radiation Safety," Rev.20. Step 9.2.3, Prior to containm Supervisor to confirm the following:	ent entry, contact the Shift
A. Phere is not flux mapping or incore detector movement dose rates and possible overexposures can be caused	
B. The Shield building ventilation systems are secured.	
C. Both the personnel and the maintenance airlocks are	unlocked. Noting
Standard:	dur ?
Candidate determines that this requirement applies and docu provided.	ments by listing on the sheet
Comment:	
CUE: None.	
CUE: None. 6 Performance step:	SAT/UNS
6 Performance step: F-2, "Radiation Safety," Rev.20. Step 9.2.4, If the unit is above	
6 Performance step: F-2, "Radiation Safety," Rev.20. Step 9.2.4, If the unit is above building door at each entry SHALL be closed at all times.	re cold shutdown, one shield

7 Performance step:	SAT/U
F-2, "Radiation Safety," Rev.20. Step 9.2.5, Before entry, a conducted with those entering and Control Room personnel briefing SHALL include a discussion of all tour/work location (PINGP 1112)	, as appropriate. This pre-jol
Standard:	
Candidate determines that this requirement applies and doc provided.	cuments by listing on the shee
Comment:	
CUE: None.	
Q. Dorformana atan	CAT/I
8_ Performance step:	SAT/U
F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel er	ntering the containment SHA
F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel er check in with the Control Room, or the designated person at When contacting Control Room prior to Containment entry a wearing a TLD and Electronic Dosimeter (ED) and the ED is	ntering the containment SHA l t the airlock, if posted. at power, ensure all, personn
8 Performance step: F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel er check in with the Control Room, or the designated person at When contacting Control Room prior to Containment entry a wearing a TLD and Electronic Dosimeter (ED) and the ED is indicated with the window). Standard:	ntering the containment SHA l t the airlock, if posted. at power, ensure all, personn
F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel er check in with the Control Room, or the designated person at When contacting Control Room prior to Containment entry a wearing a TLD and Electronic Dosimeter (ED) and the ED is indicated with the window).	t the airlock, if posted. at power, ensure all, personn s turned on (number and mRe
F-2, "Radiation Safety," Rev.20. Step 9.2.6, All personnel er check in with the Control Room, or the designated person at When contacting Control Room prior to Containment entry a wearing a TLD and Electronic Dosimeter (ED) and the ED is indicated with the window). Standard: Candidate determines that this requirement applies and doc	ntering the containment SHA l t the airlock, if posted. at power, ensure all, personn s turned on (number and mRe

9 Performance step:		SAT/UNSA
temperatures are above 85 c	2.20. Step 9.2.7, All personnel should degrees. The guidelines for heat stre Backup teams and stay times may be	ss in the NSP PINGP Safet
Standard:		
Candidate determines that the provided.	his requirement applies and documen	its by listing on the sheet
2		
Comment:		
CUE: None.		
CUE: None.		0.47/11/10
		SAT/UNSA
CUE: None. 10 Performance step: F-2, "Radiation Safety," Rev.	.20. Step 9.2.8, When all personnel a airlock hatches SHALL be locked.	SAT/UNSAre out of the containment, t
CUE: None. 10 Performance step: F-2, "Radiation Safety," Rev. personnel and maintenance		
CUE: None. 10 Performance step: F-2, "Radiation Safety," Rev. personnel and maintenance standard:	airlock hatches SHALL be locked.	re out of the containment, t
CUE: None. 10 Performance step: F-2, "Radiation Safety," Rev. personnel and maintenance standard: Candidate determines that the	airlock hatches SHALL be locked.	re out of the containment, t

(Denote critical st	teps with BOLD)		
11 Perform	ance step:		SAT/UNSAT
temperatures are	above 85 degrees. The	r, All personnel should use guidelines for heat stress s and stay times may be	in the NSP PINGP Safety
Standard:			
Candidate determ provided.	nines that this requiremen	at applies and documents	by listing on the sheet
Comment:			
CUE: None.			
12 Perform	ance step:		SAT/UNSAT
F-2, "Radiation Sa personnel and ma	afety," Rev.20. Step 9.2.8 iintenance airlock hatche	, When all personnel are s SHALL be locked.	out of the containment, the
Standard:			
Candidate determ provided.	ines that/this requiremen	t applies and documents	by listing on the sheet
Comment:			
CUE: None.		Solo X	

(Denote	critical	steps	with	BOL	D)	
---------	----------	-------	------	-----	----	--

13 Performance step: CRITICAL STEP

SAT/UNSAT

F-2, "Radiation Safety," Rev.20. Step 9.3.2, B. If R-11 and R-12 of the appropriate Unit are:

- 1. Not alarming and normal readings, entry may be made without any respiratory protection.
- 2. Alarming on scale, entry may be made with the use of a MSA Ultralite II.
- 3. Alarming off scale, no entry may be made without the Supt. Rad Protection or designee appraisal and approval.

Standard:

Candidate determines that this requirement (3) applies and documents by listing on the sheet provided.

Comment:

CUE: If asked inform the candidate that R11 and R 12 are alarming OFF scale.

Terminating cue: When the candidate determines that all F-2 requirements are listed.

	Appendix	<u>C</u>
--	-----------------	----------

Form ES-C-1 (R8, S1)


VERIFICATION OF COMPLETION
Job Performance Measure No
Examinee's Name:
Examiner's Name:
Date performed:
Facility Evaluator:
Number of attempts:
Time to complete:
Question Documentation:
Question:
Response:
Result: SAT or UNSAT
Examiner's signature and date:

Initial Conditions:

Unit 1 is operating. (

An alarm on Fire Protection Panel FP121 indicates there is a fire in Zone 20.

Initiating Cues:



The SM has directed you to list all the requirements that must be met to allow the fire brigade access to the affected zone.

B 9.24 ONE DUDE CLOSED IN EASTH SHIELD BEDG. D HOLD PRE-JOB BRIEZ PING 1112 D CONTACT CONTROL ROOM PLIOR TO ENTRY B BACKUP TEAMS - STAY TIMES BAPED ON HEAT STRESS		Requirements	
D NO ENTRY INTO RC WIRS - RX CAUTY 3. BROWN NO FUNY MAP IN PROGRESS 4) SBVS FECURED B 9.24 ONE DUDE CLOSED IN EASTH SHIELD BEDG. 6) HOLD PRE-SOB BRIET PING 1112 9) CONTACT CONTROL ROOM PLIOR TO ENTRY 8) PACKUP TEAMS - STAY TIMES BAPED ON HEAT STRESS 9) 1841 -1812 NOT ALARMING OR RAO PROTECTION APPROVAL		ENTRY TEAM SHALL BE ETULIPPED W/DOSIM	27
3. DABONO FUNY MAP IN PROBLESS 4) SBVS FECURED B 9.24 ONE DUDE CLOSED IN EASTH SHIELD BEDGE 6) HOLD PRE-SOD BRIEZ PING 1112 7) CONTACT CONTROL POOM PLIOR TO ENTRY 8) BACKUP TEAMS - STAY TIMES BASED ON HEAT STRESS 9) 1841 -1812 NOT ALARMING OR PAO PROTECTION APPROVAL	TL	- BETA GAMMA PURITY INST.	
(4) SBVS SECURION BY 9.24 ONE DUDE CLOSED IN EASTH SHIELD BEDGE BY HOLD PRE-SOA BRIET PING 1112 TO CONTACT CONTROL POOM PLIOR TO ENTRY BY BACKUP TEAMS - STAY TIMES BARED ON HEAT STRESS J 1811 -1812 NOT ALARMING OR PAO PROTECTION APPROVAL	D	NO ENTRY INTO RC WIPS - PK CAUITY	
(4) SBVS FECURIO. (5) 9-24 ONE DUDL CLOSED IN EARCH SHIELD BLOG. (6) HOLD PRE-SOA BRIET PING 1112 (7) CONTACT CONTROL POOM PLIOR TO ENTRY (8) BACKUP TEAMS - STAY TIMES BAPED ON HEAT STRESS (9) 1811-1812 NOT ALARMING OR PAO PROTECTION APPROVAL	3.	DOB NO FULLY MAP IN PROGRESS	
100 PRE-500 BRIEZ PING 1112 10 CONTACT CONTROL POOM PLIOR TO ENTRY 10 BACKUP TEAMS - STAY TIMES BARED ON HEAT STRESS 1 1411 -1812 NOT ALARMING OR PAO PROTECTION APPROVAL	<u>(4)</u>		
6) HOLD PRE-SOM BRIEZ PING 1112 9) CONTACT CONTROL ROOM PLIOR TO ENTRY 8) BACKUP TEAMS - STAY TIMES BARED ON HEAT STRESS 9 1841 -1812 NOT ALARMING OR RAO PROTECTION APPROVAL	8	1.24 ONE DUDE CLOSED IN EASTH SHIELD BEDG.	
B BACKUP TEAMS - STAY TIMES BAPED ON HEAT STRESS 9 1811 -1812 NOT ALARMING OR PAO PROTECTION APPROVAL	ه		
B BACKUP TEAMS - STAY TIMES BAPED ON HEAT STRESS 9 1811 -1812 NOT ALARMING OR RAD PROTECTION APPROVAL	9)	Contract CONTROL ROOM PLIOR TO ONTRY]
	<u> </u>	•	
6 OBSERVE RWF	9	41 -1RIZ NOT ALARMINO OR PAO PROTECTION APPROVAL	
	6	SPECIE RWP	7
			1
			1

KEY

	Requirements		
1. \$	Stop Power Increase		
2.	Entry team equipped with TLD's, Dosimeters, and a beta-gamma survey instrument.		
3. 1	Need permission of Supt. of Radiation Protection and Chemistry to enter RC loop area		
4. (and t	Contact SS and verify that no flux mapping or incore detector movement is in progress that shield building ventilation is secured.		
5. I	If in Mode 1 then one shield building door at each entrance must be closed.		
6. F	Pre-job brief		
7. (Check in w/control room and verify TLD & ED is on		
8. V	When containment temperatures are above 85° review guidelines in safety manual.		
9. N	MSA Ultralite II required for entry		
10. F	Follow RWP requirements.		

Key

6

OTNG 666

7/17/07 Q 57. RU OP TEST AH

Church seconnadably

Appendix C

Job Performance Measure Worksheet

Form ES-C-1 (R8, S1)

Facility: <u>Prairie Island</u>		Task No:							
rask fille. <u>Efficigeticy</u>	NAC Notification	Job Performance Measure No: RO A.4							
K/A Reference: _K/A 2.	4.12 [3.4/3.9]								
Examinee:		NRC Examiner:							
Facility Evaluator:		Date:							
Method of testing:									
Simulated Performance	_X_ Actual Perform	mance Classroom Simulator Plant							
READ TO THE EXAMIN	EE	•							
cues. When you comple	I will explain the initial conditions, which steps to simulate or discuss, and provide initiating cues. When you complete the task successfully, the objective for this job performance measure will be satisfied.								
Initial Conditions: A General Emergency been notified.	vwas declared 33 m	ninutes ago. The NRC Operations Center has not yet							
Task Standard: The candi NRC opera	date must demonstr ations center on a co	trate that he/she understands the capability to call the commercial telephone line.							
Required Materials:	Copy of PINGP 66	66, Rev. 17.							
General References:	F3-4, "Responsibili Emergency"	ities During An Alert, Site Area, or General							
Initiating Cues:									
The Unit 2 SS directs NRC operations center	you to make an im er due to a declarat	nmediate emergency notification phone call to the tion of a General Emergency 33 minutes ago.							
Time Critical Task: YES/	NO Alte	ernate Path: YES/ <u>NO</u>							
Validation Time: M	linutes Time Starte	ed Time Finished:							

Ap	pen	dix	C

Form ES-C-1 (R8, S1)

PERFORMANCE INFORMATION

(Denote c	critical steps with BOLD)	
P	Performance step:	SAT/UNSAT
OBTAIN F	PINGP Form 666.	
Standard:	:	
	idate understands that a prepared form exists and needs to be cting the NRC.	completed prior to
Comment	t :	
CUE:	When the candidate asks for a copy of PINGP Form 666 prov	vide a pre-filled out



SIMULATE contacting the NRC Operations Center.

Standard:

Provide the evaluator with one of the commercial numbers for calling the NRC Ops Center from the top of PINGP Form 666 and simulate calling the NRC Ops Center within 27minutes of being assigned this task.

Comment:

Cue:

When the candidate picks up the Red Phone inform the candidate that the phone does not work.

Terminating cue:

When the candidate provides the commercial number to the evaluator the JPM is complete.

Appendix C	Form ES-C-1 (R8, S1
VERIFICAT	TION OF COMPLETION
Job Performance Measure No	
Examinee's Name:	
Examiner's Name:	
Date performed:	
Facility Evaluator:	
Number of attempts:	
Time to complete:	
Question Documentation:	
Question:	
Response:	

Result: SAT or UNSAT

Examiner's signature and date: _____

Initial Conditions:

 A General Emergency was declared 33 minutes ago. The NRC Operations Center has not yet been notified.

Initiating Cues:

The Unit 2 SS directs you to make an immediate emergency notification phone call to the NRC operations center due to a declaration of a General Emergency 33 minutes ago.

Initial Conditions:

 A General Emergency was declared 32 minutes ago. The NRC Operations Center has not yet been notified.

Initiating Cues:

The Unit 2 SS directs you to make an immediate emergency notification phone call to the NRC operations center due to a declaration of a General Emergency minutes ago.

PINGP 666, Rev. 17 Page 1 of 2 Retention: Life

Document Type: 7.36F

	FORM 361 000)				FVFN	NT NOT	IFICATIO	N W)BKSHE	FT		U.S. NUCLEAR R COMMISSION OPERATE	
NRC	OPERATION TELEPH	ONE NU	MBER I								800-44	19-3694*,	
	301-415-0550 and [3rd FICATION TIME			OR ORGAN	IZATIO		sees who maint				ese te	ephone numbers CALL BACK #	
$\rho_{\rm a}$													
		- 14	KAK	(16 156	LAN	O	1						
EVEN	IT TIME & ZONE	1	EVENT D	ATE			POWER/MC	DE BEI	ORE			POWER/MODE AFTER	
							100	2%			1	0%	
	EVENT CLAS	SIFICA	TIONS		1-	Hr. Non-E	mergency 10	CFR 5	i0.72(b)(1)		(v)(A) Safe S/D Capability	AINA
Х	GENERAL EMERGE	NCY		ENVAAEC		тт	S Deviation		ADE	v	(v)(B) RHR Capability	AINB
	SITE AREA EMERGI	ENCY		SIT/AAEC	4-	Hr. Non-E	mergency 10	CFR 5	0.72(b)(2)		(v)(C) Control of Rad Release	AINC
	ALERT			ALE/AAEC		(i) T	S Required S/D		ASH	<u> </u>	(v)(D) Accident Mitigation	AIND
	UNUSUAL EVENT		L	INU/AAEC		(iv)(A) E	CCS Discharge	to RCS	ACC	s	(xii)	Offsite Medical	AMED
	50.72 NON-EMERGE	NCY	(see ne	ext columns)		(iv)(B) R	PS Actuation (s	cram)	ARP	s	(xiii)	Loss Comm/Asmt/Resp	ACCM
	PHYSICAL SECURIT	Y (73 7	1)	DDDD			Msite Notificatio		APR	Ε,	60-D	ay Optional 10 CFR 50.73	(a)(1)
	MATERIAL/EXPOSU	RE		B???	8-	Hr. Non-E	mergency 10	CFR 5	0.72(b)(3)			Invalid Specified System A	
	FITNESS FOR DUTY			HFIT			egraded Condit		ADE		her U	nspecified Requirement	(Identify)
	OTHER UNSPECIFIE		MT (see			(ii)(B) U	nanalyzed Cond	dition	AUN	<u> </u>		<u></u>	NONR
	INFORMATION ONL	Υ		NNF		(iv)(A) S	pecified System		on AES	F			NONR
la al	de: Systems affecte				-4'		DESCRIPTI			· · · · · · · · · · · · · · · · · · ·			
NOTIF	FICATIONS	YES	NO	WILL DO	A 8 11 /-	LINO I TO							
	RESIDENT	153	 "" 	WILL BE		HING UNU UNDERSTO			/ES (Explain	ahove)		NO	
STATI			\vdash			LL SYSTEM			co (explain	accive			
100A		 -	\vdash			TION AS R			(ES			NO (Explain above)	
	R GOV AGENCIES		\vdash					لب				ADDITIONAL INFO	ON BACY
	VPRESS RELEASE		 -		1	E OF OPER L CORREC'			}	ESTIMATE RESTART		YES NO	UN DACK
	ORM 361 (12-2000)			L	L		- -						

ADDITIONAL INFORMATION

SECONORE MELENOL	J. CITEON OITHER W		T T T T T T T T T T T T T T T T T T T		1 1 2 2				т.	
	IQUID RELEASE GASEOUS RELEASE IONITORED UNMONITORED ERSONNEL EXPOSED OR CONTAMINATED		OFFSITE RE		PLANNED RELEASE T S EXCEEDED					TERMINATED AREAS EVACUATED
			L	OFFSITE PROTECTIVE ACTIONS RECOMMENDED					* State release path in description	
		1	L							T
	Release Rate (C/sc	xc)	% TS LIMIT	H00 0		Total Activity (Ci)		%TS LIMI	T	HOO GUIDE
Noble Gas lodine				10 µC	Vsec	-				0010
Particulate				1 _{بر} 1						1 mCi
Liquid (excluding tritum & dissolved noble gases)				10 μC	Cv/men					0.1 G
Liquid (tritium)				020	i/min					5 C
Total Activity				<u> </u>			l			!
	PLANT	STACK	CONDENSER	AIR EJECTOR		MAIN STEAM LINE	s	G BLOWDON	VN	OTHER
RAD MONITOR READINGS	•									
% T.S. LIMIT (# applicable)	<u> </u>						+			· · · · · · · · · · · · · · · · · · ·
RCS OR SG TUBE LEAKS: LOCATION OF THE LEAK			TEMS (Specific Deta	ars/expranations	should be con	valued in event description	·/			
LEAK RATE:		UNITS gpm	/gpd		TS LIMITS	· · ·		SUDDEN	OR LONG	S TERM DEVELOPMENT
LEAK START DATE	TIME				COOLANT AND UNITS		YRAMIR	<u> </u>	SECO	ONDARY
OF SAFETY RELATED	D EQUIPMENT NOT O	PERATIONAL								
NOTE: PLANT IN	FORMATION C	DNLY								
Event Number	<u> </u>									
NRC Contact Pers	on:									
Telecopy to NRC (•		•						(initia	•
Telecopy to Xcel A	sset Manager (612-330-6	6938):						(initia	•
Telecopy to Xcel C		•							(initia	•
Telecopy to Xcel P									(initia	·
Telecopy to NMC I	Regulatory Serv	rices (715	-377-3355):						(initia	•
Notify NMC Regula	atory Services th	hat form v	vas faxed (715	5-377-3379):				_(initia	al)
Copy Given to Ope	erations SS or S	SM:							_(initia	al)
Copy Given to Site	Communication	ns:							_(initia	als)
Copy Given to NR	C Resident Insp	ector:	_						_(initi	al)
Copy Sent to Gen.	Supt. Operation	ns:							(initi	al)
y Given to Rac	J. Prot. Emerg. I	Planner: _	··································			 		<u> </u>	(initi	al)
Original Given to S	ite Licensing: _				nitial)		(Date	.)	_	
				(1	riillai)		(Date	7)		

•							_
Δ	n	n	Δ	n	а	iχ	()
_	v	v	C	,,	u	ıĸ	$\mathbf{}$

Job Performance Measure Worksheet

Form ES-C-1 (R8, S1)

Facility: Prairie Island	Task No:
Task Title: Classify an Event, Initiate Protective Action Recommendations, and Complete Emergency Notification Report Form PINGP 577 K/A Reference: 2.4.38 [4.0]	Job Performance Measure No: SRO A.4
Examinee:	NRC Examiner:
Facility Evaluator:	Date:
Method of testing:	
Simulated Performance X Actual Performance _	_ Classroom _X_ Simulator Plant
READ TO THE EXAMINEE	

I will explain the initial conditions, which steps to simulate or discuss, and provide initiating cues. When you complete the task successfully, the objective for this job performance measure will be satisfied.

Initial Conditions:

- Unit 1 has had an automatic Reactor Trip and Safety Injection from 100% power
- 1E-0, "Reactor Trip or Safety Injection" is in effect at step 8
- Unit 1 plant conditions are as follow:
 - Offsite power has been lost to Unit 1
 - RCS pressure is at 1100 psig and slowly decreasing
 - Core exit TCs are at 750°F and slowly increasing
 - Containment pressure is at 10 psig and slowly decreasing
 - No SI pumps are available
 - All three (3) Charging Pumps are running with charging flow at 120 gpm
 - RVLIS full range level is at 35% and decreasing
 - A and B SG pressures are at 900 psig and stable
 - The containment in-service purge system was in operation prior to the Reactor Trip and Safety Injection
 - Containment in-service purge exhaust valves CV-31310 and CV-31311 do NOT indicate full closed by their status lights
- Unit 2 is at 100% power with all equipment in normal lineup

Task Standard:

- CLASSIFY the event as a GENERAL EMERGENCY
- PROVIDE correct Protective Action Recommendations (PARs)
- DOCUMENT the classification and PARs on the Emergency Notification Report Form (PINGP 577)

Appendix C	Job Pe	rformance Measure Worksheet	Form ES-C-1 (R8, S1)
Facility: Prairie Island	<u> </u>	Task No:	
and Comp	n Event, Initiate Action Recommend Diete Emergency No orm PINGP 577	dations.	ce Measure No: <u>SRO A.4</u>
K/A Reference: 2.4.	38 [4.0]		
·	 PINGP 577, F3-8.1, "Rec On Shift Em F3-13.5, "All PINGP 1125 	sifications of Emergencies "Emergency Notification commendations for Offsite ergency Director / Shift M ternate Meteorological Da 5, "Control Room Shift Ma Director Checklist", Rev 1	Report Form", Rev 28 e Protective Actions for the lanager", Rev 12 ta", Rev 4W nager / Shift Supervisor
	2. PINGP 577, 3. F3-8.1, "Red On Shift Em 4. F3-13.5, "Alt 5. PINGP 1125 Emergency	ifications of Emergencies "Emergency Notification commendations for Offsite ergency Director / Shift M ternate Meteorological Da 5, "Control Room Shift Ma Director Checklist", Rev 1 Cooling", Rev 4	Report Form", Rev 28 30 Protective Actions for the lanager", Rev 12 ta", Rev 4W nager / Shift Supervisor
nitiating Cues:			
- CLASSIFY the - COMPLETE PI	event per F3-2, and NGP 577, "Emerge	ncy Notification Report Fo	
Fime Critical Task: YE (15)		Alternate v event) ete PINGP 577	e Path: YES/ <u>NO</u>

add to ensure that the time it to key to classify the event is obtained

(Oncor. Changes incorporated Centimemens). Maloz

	PERFORMANCE I	NFORMATION
(Denote critical steps with B	OLD)	
1 Performance step:	CRITICAL STEP	SAT/UNSAT
		el and Emergency Action Level (EAL) per ment 1 based on the Initial Conditions
Standard:		
	el to be EAL Referen ified.	vel to be a GENERAL EMERGENCY and ce Manual Condition Number 6 based on to classify event).
Comment:		
2_ Performance step:	CRITICAL STEP	SAT/UNSAT
•		PINGP 577,
Standard:	tion Recommendation	ons per PINGP 1125 or F3-8.1, Figure 1
olaridard.		PIN 61 577,
DETERMINE Protective Acto be:	tion Recommendation	ons per PINGP 1125 or F3-8.1, Figure 1
	ors out to 2 miles, an	
	ownwind sectors out	to 5 miles, and itor radio / TV broadcasts for further
emergency informa	-	itor radio / 14 broadcasts for further
Comment:		
- CIRCLE SUBAREA SUBAREA "Z" LL	s " 5W and 5N" of all o	n addition to ed on the form
· = - = -		

Corxur. Changes incorporated.

Millor

(Denote	critical	steps	with	BOLD
---------	----------	-------	------	------

____3_ Performance step:

CRITICAL STEP

SAT/UNSAT

DOCUMENT the classification and PARs on the Emergency Notification Report Form (PINGP 577).

Standard:

DOCUMENT the classification and PARs on the Emergency Notification Report Form (PINGP 577) per the following:

- Section 1.2 We have "(a) Declared" a "(4) General Emergency"
- Section 1.3 The emergency "(b) DOES involve an airborne radioactive release
- Section 1.4 The protective action recommendation at this time is:

Changes to reflect
Sectors, subaresus for
Coordinan specified
On form PINGP 5717
Meteorological Data.

(a) Evacuate ALL sectors out to 2 miles, MINIGOR REVACUATE THE 5 downwind sectors "N,P,O,R,A" out to 5 miles

CIRCLE SUBAREAS "5N, 5E, 5S, and 5W" in addition to SUBAREA "2" that is already circled on the form

 Advise remainder of plume EPZ to monitor radio / TV broadcasts for further emergency information

Section 2.1 - The EAL Reference Manual Condition Number is 6

Section 2.2 - Affected sectors MINIPIDIR

Comments Section 2.3 - Sign approved of form

add to reflect other Hems filled out on form.

Terminating cue:

Concur. Changes incorporated.

•						•	_
Λ	~	~	\sim	~	~		
~	I)	IJ	•		a	ıx	

5

Form ES-C-1 (R8, S1)

VERIFICATION OF COMPLETION
Job Performance Measure No
Examinee's Name:
Examiner's Name:
Date performed:
Facility Evaluator:
Number of attempts:
Time to complete:
Question Documentation:
Question:
Response:
Result: SAT or UNSAT
Examiner's signature and date:

Initial Conditions:

- Unit 1 has had an automatic Reactor Trip and Safety Injection from 100% power
- 1E-0, "Reactor Trip or Safety Injection" is in effect at step 8
- Unit 1 plant conditions are as follow:
 - Offsite power has been lost to Unit 1
 - RCS pressure is at 1100 psig and slowly decreasing
 - Core exit TCs are at 750°F and slowly increasing
 - Containment pressure is at 10 psig and slowly decreasing
 - No SI pumps are available
 - All three (3) Charging Pumps are running with charging flow at 120 gpm
 - RVLIS full range level is at 35% and decreasing
 - · A and B SG pressures are at 900 psig and stable
 - The containment in-service purge system was in operation prior to the Reactor Trip and Safety Injection
 - Containment in-service purge exhaust valves CV-31310 and CV-31311 do NOT indicate full closed by their status lights
- Unit 2 is at 100% power with all equipment in normal lineup

(oncor. Charges (enhancements).
incorporated (enhancements).

Initiating Cues:

The Unit 1 Shift Supervisor has asked you, as the unaffected Unit 2 Shift Supervisor, to:

CLASSIFY the event per F3-2, and

COMPLETE PINGP 577, "Emergency Notification Report Form",

which has been partially filled out.

The Shift Emergency (communicator (SEC) has abtained the Meteorological Data and it has been placed on the partially.

This is a Time Critical Task. filled out PINGP 577 form

NOTIFY the Unit 1 Shift Syponison (eveletor) at the time you declare the Event Classification, and